
UNITED STATES
SECURITIES AND EXCHANGE COMMISSION
Washington, D.C. 20549

Form 8-K

CURRENT REPORT

PURSUANT TO SECTION 13 OR 15(d) OF THE
SECURITIES EXCHANGE ACT OF 1934

Date of Report (Date of earliest event reported) February 5, 2006

PORTLAND GENERAL ELECTRIC COMPANY

(Exact name of registrant as specified in its charter)

Oregon

(State or other jurisdiction of
incorporation or organization)

Commission File Number

1-5532-99

93-0256820

(I.R.S. Employer
Identification No.)

121 SW Salmon Street, Portland, Oregon 97204

(Address of principal executive offices) (zip code)

Registrant's telephone number, including area code: **(503) 464-8000**

Check the appropriate box below if the Form 8-K filing is intended to simultaneously satisfy the filing obligation of the registrant under any of the following provisions:

- Written communications pursuant to Rule 425 under the Securities Act (17 CFR 230.425)
 - Soliciting material pursuant to Rule 14a-12 under the Exchange Act (17 CFR 240.14a-12)
 - Pre-commencement communications pursuant to Rule 14d-2(b) under the Exchange Act (17 CFR 240.14d-2(b))
 - Pre-commencement communications pursuant to Rule 13e-4(c) under the Exchange Act (17 CFR 240.13e-4(c))
-

Section 8 - Other Events

Item 8.01 Other Events

Boardman Coal Plant Outage

Portland General Electric Company (PGE, or the Company) has a 65% ownership share of a 585 MW coal-fired generating plant located in Boardman, Oregon (Boardman). As previously reported in PGE's Form 8-K dated November 18, 2005, Boardman was taken out of service on October 22, 2005 for repairs to the turbine rotor. The turbine rotor was repaired and on February 6, 2006, during the process of returning the plant to operation, the generator rotor was damaged. The generator rotor has been removed for further examination and repairs.

Although the actual time required to repair the generator rotor has not been determined, PGE estimates that Boardman may not be operational until the end of March 2006, or later. The unplanned outage has required PGE to replace its portion of Boardman's generation with increased generation from the Company's natural gas-fired generating plants and wholesale market purchases. Current market prices for natural gas and power purchases are significantly higher than Boardman's variable costs used in setting customer rates. It is anticipated that, depending on market prices, PGE's estimated cost of replacing its share of Boardman's generation during the generator rotor repair period will be \$350,000 to \$500,000 per day in excess of the estimated power costs used in setting rates for 2006.

On November 18, 2005, PGE filed with the Public Utility Commission of Oregon (OPUC) an "Application for Deferred Accounting of Excess Power Costs Due to Plant Outage" (Application). The Application requested an order authorizing PGE to defer for later ratemaking treatment excess power costs associated with Boardman's turbine rotor outage, effective on the date of the Application. The Application seeks deferral of the difference between Boardman's variable power costs used in setting rates for 2005 and 2006 (under the Company's Resource Valuation Mechanism) and replacement power costs incurred during the turbine rotor outage. The deferral period for the outage ended on February 5, 2006 with the installation of the repaired turbine rotor. Management cannot predict the timing or the ultimate outcome of a decision by the OPUC on the Company's Application.

PGE is currently evaluating whether to file a new deferred accounting application with the OPUC for the deferral of excess replacement power costs for the outage period, beginning February 6, 2006, resulting from the damage to the generator rotor.

